

Added position of holes for horizontal and vertical Plug-in terminal block. - 25/01/2011 M.F.